






## CTL-608 & 609 Current Interrupter Circuit Card Selection

Please view the pictures below. When ordering a replacement circuit board, you must specify the model of the current interrupter as a different program is required for different models.

	<p>CI-97</p> <ul style="list-style-type: none"> <li>• Two boards joined together with GPS engine attached elsewhere on faceplate.</li> <li>• No longer supported, upgrade to new board and GPS is possible</li> </ul>
	<p>CI-2000</p> <ul style="list-style-type: none"> <li>• One board with very large GPS engine, Garmin 25.</li> <li>• No longer supported, upgrade to new board and GPS is possible.</li> </ul>
	<p>CI-2001</p> <ul style="list-style-type: none"> <li>• Board with Trimble engine.</li> <li>• No longer supported, some supplies still available, GPS Trimble engines still available.</li> <li>• Upgrade to new board and GPS is recommended.</li> </ul>
	<p>CI-2002</p> <ul style="list-style-type: none"> <li>• Board without onboard GPS engine for Garmin 18 and 18x.</li> <li>• Replacement boards still available.</li> </ul>
	<p>CI-2010</p> <ul style="list-style-type: none"> <li>• Attaches directly behind the display.</li> <li>• Latest board, compatible with GPS 18 and 18x.</li> </ul>